

Silo Level Measurement

Monitor the level and volume of storage in your remotely located grain silos.

Maximise the utilisation of silo capacity and product through reliable measurement.

Real-time level or volume indication for supply and replenishment.

One remote monitoring solution whether you use weight, ultrasonic, radar or laser measurement.



Use the voltage input on the ORB-X1 to measure weight output from a load-cell.

The serial and duty-cycle inputs on the ORB-X1 connect to most ultrasonic, radar and laser measurement systems.

Receive real-time level and volume measurements.

Set minimum and maximum warning and alarm levels for material levels and volumes.

